

UNIT NUMBER SWMU 105

UNIT NAME Rubble pile 3

REGULATORY STATUS: AOC

LOCATION: East of Dykes Road S-2800 W-4000

APPROXIMATE DIMENSIONS: Dam approx. 20 ft long and 10 ft wide - concrete in
and on dam approx. 150 sq ft of concrete visible

FUNCTION: Provides skimming and sampling of drainage

OPERATIONAL STATUS: active

DATES OPERATED: 1981 to present

SITE/PROCESS DESCRIPTION: None

WASTE DESCRIPTION: Concrete slabs from road construction spoils

WASTE QUANTITY: Volume unknown, approx. 50 cu yards of concrete. bed gravel,
and dirt

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Beta/gamma survey found no contamination on
rubble. Soil Gamma scan found no detectable soil
contamination.

RFI NECESSARY: YES



